

## Approved mobile phones for the Audi Bluetooth™ car phone (SIM access)

Telephone type		Access to SIM card phonebook	Access to internal phonebook	Tested mobile telephon firmware version <sup>1</sup>
BenQ Siemens	CX75	yes	yes	09
	EL71	yes	yes	17
	M75	yes	yes	23
	S65	yes	yes	50
	S68	yes	yes	38
	S75	yes	yes	20
	SK65	yes	yes	50
	SL75	yes	yes	20
	SP65	yes	yes	50
Nokia	3109	yes	yes	5.30
	3110c	yes	yes	5.30
	3250	yes	no	3.18
	5200	yes	yes	5.00
	5300	yes	yes	5.00
	6021	yes	yes	3.83
	6103	yes	yes	4.61
	6110 Nav	yes	no	3.51
	6111	yes	yes	3.58
	6125	yes	yes	3.51
	6230	yes	yes	5.24
	6230i	yes	yes	3.40 - 3.70 - 3.80 - 3.81
	6233	yes	yes	5.43
	6234	yes	yes	5.43
	6270	yes	yes	3.53
	6300	yes	yes	5.00
	6820	yes	yes	5.30
	6822	yes	yes	4.46
	7370	yes	yes	3.52
	7373	yes	yes	5.00
	8800	yes	yes	3.94
	9300 <sup>2</sup>	yes	no	5.22(01)
	9300i	yes	no	5.50(00)
	9500	yes	no	5.22
	E50	yes	no	7.13.00
	E60	yes	no	1.0610.02.15
	E61	yes	no	3.0633.09.04
	E61i	yes	no	1.0633.22.05
	E65	yes	no	1.0633.18.01
	E70	yes	no	1.0610.05.06
	N71	yes	no	2.0613.1.12.1
	N73	yes	no	4.0726.2.0.1
N80	yes	no	3.0614.0.3 - 4.0623.0.41	
N91	yes	no	1.00.028.02	
N93	yes	no	20.0.058	
N95	yes	no	12.0.013	

**No responsibility is taken for the accuracy of this information. Last revised 23.08.2007**

If a mobile phone is not listed, either it has not been tested or its effective operation cannot be assured. In some cases, you may experience problems with one or other of the phones listed.

Operation using the hands-free profile is not recommended.

1 All information related to the mobile-phone software version tested. Similar functionality is to be expected from newer versions of the same software. This cannot, however, be guaranteed. Should performance be impaired when using a mobile phone with older software and mobile preparation with Bluetooth interface, a newer version of the software may offer a solution.

2 SAP only after mobile phone firmware status 5.22. The input time for the Bluetooth™ pin is limited to 20 seconds.

SMS-Function: Only the messages saved on the SIM card are displayed.

With some of the listed telephones, you will not receive any indication of unread messages on your mobile phone display after ending the SIM access connection. In this case, please look for the SMS symbol in the MMI or check the message folder on your telephone after disconnecting the SIM access. For more information, please see the operating instructions for your phone.

## Read out firmware status of a mobile phone

If your mobile phone does not work with the Audi Bluetooth™ car phone, even though it is included in the above-mentioned list, there could be a problem with the firmware status of your mobile phone. Please see the table to find out which firmware status you should use. You can find out the software version of your mobile phone by making the following inputs on your mobile phone keypad:

### **BENQ Siemens**

Display software version	*#06# and the left-hand display key
--------------------------	-------------------------------------

### **Nokia**

Display software version	*#0000#
--------------------------	---------

You can obtain a firmware update for your mobile phone from the manufacturer of the phone or from your mobile communications provider.

With BenQ-Siemens mobile phones, you can also download the software yourself via the Internet.

<http://www.benqmobile.com>

<http://www.nokia.com>

If you have any further questions about the Audi Bluetooth™ car phone, please contact your Audi Partner or go to [www.audi.com](http://www.audi.com)